


**1
2
VOLT**

GO BUGGY GO!

cod.IGOR0035

CE



IT USO E MANUTENZIONE

EN USE AND CARE

FR UTILISATION ET ENTRETIEN

DE GEBRAUCH UND WARTUNG

ES EMPLEO Y MANUTENCION

PT USO E MANUTENÇÃO

SL UPORABA IN VZDRŽEVANJE

DA BRUGSANVISNING

FI KÄYTTÖOHJE

NO BRUKSANVISNING

SV BRUKSANVISNING

TR KULLANIM VE BAKIM

RU ЭКСПЛУАТАЦИЯ И УХОД
















EL ΧΡΗΣΗ ΚΑΙ ΣΥΝΤΗΡΗΣΗ
















AR الاستخدام و الصيانة
















Peg-Pérego




made in italy

FI000801G119









- 1 SAGI8851GR
- 2 SPST8850VD
- 3 SPST8849YK
- 4 SPST8855LS
- 5 SPST8856N
- 6 IAKB0019
- 7dx SPST8857GR
- 7sx SPST8857JGR
- 8 SAGI9962KXK
- 9 SOFF0245Z
- 10 SAGI8843GRGR
- 11 SPST8840YK
- 12 SPST8841VD
- 13 SPST0467KGL
- 14 SPST8837GR
- 15 SPST8836VD
- 16dx SPST8859D
- 16sx SPST8859S
- 17 SPST8848YK
- 18 SPST8861YK
- 19 MUCI1006GR
- 20 ICB...
- 21 MEVA0045
- 22 MMEV0463
- 23 SAGI8993GRVD

